

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:						
Company	Dennis Ware Controller					
OGM	Joe Helfrich Environmental Scientist III					

Inspection Report

Permit Number:	C0070038		
Inspection Type:	TECHNICAL		
Inspection Date:	Wednesday, April 06, 2005		
Start Date/Time:	4/6/2005 11:00:00 AM		
End Date/Time:	4/6/2005 2:00:00 PM		
Last Inspection:	Thursday, March 17, 2005		

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny 55

InspectionID Report Number: 592

Accepted by: whedberg 5/5/2005

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE

Address: 847 NW HWY 191, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Types of Operations Mineral Ownership

14,670.00 T	Total Permitted	✓ Federal	✓	Underground
161.55 T	Total Disturbed	☐ State		Surface
	Phase I	☐ County	✓	Loadout
	Phase II	✓ Fee		Processing
	Phase III	✓ Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to evaluate the erosion potential on the property being turned over to the Price River Water district. The permittee is preparing a phase three application for bond release on this property. I was accompanied by Dennis Ware, controller for the company. The property to be evaluated for erosion potential was walked in it's entirety and photos were taken.

Inspector's Signature **Date**

Tuesday, April 26, 2005

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070038 Inspection Type: TECHNICAL

Inspection Date: Wednesday, April 06, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038
Inspection Type: TECHNICAL

Inspection Date: Wednesday, April 06, 2005 Page 3 of 3

4.a Hydrologic Balance: Diversions

The eastern portion of the property slopes toward the reclaimed roughened area and a well graded rip rapped diversion ditch. Recent storms have shown no signs of erosion. The remaining portion of the property slopes to the south west into a portion of the reclaimed area and a well vegetated ditch. Runoff from all locations on this property will remain inside the reclaimed area and does not show signs of developing erosion.